	Туре	Type Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
, -	BRS	0	(429/12-46.ccls. or h01m008\$.ipc.) and (interconnector with integral\$3 adj burn\$3)	USPAT; US-PGPUB; 2001/10/24 EPO; JPO; 18:23 DERWENT	2001/10/24 18:23		
7	BRS	4	(429/12-46.ccls. or h01m008\$.ipc.) and integral\$3 adj burn\$3	USPAT; US-PGPUB; 2001/10/24 EPO; JPO; 18:25 DERWENT	2001/10/24 18:25		
3	BRS	21	(429/12-46.ccls. or h01m008\$.ipc.) and integral\$3 adj sinter\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/10/24 18:25		
4	BRS	2	((429/12-46.ccls. or h01m008\$.ipc.) and integral\$3 adj sinter\$3) and interconnector	USPAT; US-PGPUB; 2001/10/24 EPO; JPO; 18:25 DERWENT	2001/10/24 18:25		